



Revox Multiuser Update

Dear Revox Partner,

We are continuing to work diligently on the Multiuser System in the new year and are thus pleased to provide you with a new software update. The update to version 0.6.0 includes great enhancements, changes and improvements.

Read all the details in this newsletter.

Information on this update and the latest documentation can also be found on our support page www.support-revox.de.

We wish you continued good business with the Revox Multiuser products.

Your
Revox Team

New Multiuser 3.0 Update

A new software update 0.6.0 for the Multiuser 3.0 system is currently available on our online update server.



This update is automatically installed in the background on the **STUDIOMASTER M500 / STUDIOMASTER M300 / V400** Multiuser Server if the last update with OS version 0.5.2 has already been activated. After version 0.6.0 has been installed on the system, an update icon appears in place of the settings icon in the top left of the app. Touching the update icon opens the settings with the device list. The update only takes effect when the update icon is acknowledged by tapping it and the system is restarted.

The most important new features and adjustments in version 0.6.0:

- **Change in the zone service!**

With the Multiuser Update 0.6.0 we have made an important change to the zone service. This change will lead to a one-time reset of the rooms assigned to a zone after the update.

This means that all configured zones will still be available after the update, but the zones will no longer contain any rooms. The rooms can be reassigned via the multiuser app in the zone settings (3-point menu). In future, this change will mean that rooms must be explicitly added to zones and are not automatically included in zones.



Version 0.6.0 increases the available zones per multiuser server as follows:

- The **STUDIOMASTER M500/M300** now includes 8 zones
- The **V400** Multiuser Server now includes 16 zones.


Detailed information on the new scope of services and the limitations of the system can be found [here in the updated document](#) and, as usual, on our support page.

- **Maximum number of rooms in the system increased**

The maximum number of rooms per system has been increased from 32 to 63.

Note:

The maximum number of permitted sub-room amplifiers per system depends on the network connection type. You can also find out which server and connection constellation allows how many rooms in the updated document "Multiuser 3.0 - Scope of services and limitations"



- **STUDIOMASTER Deep Standby and update activation**

With the new update 0.6.0, the deep standby mode on the **STUDIOMASTER M500/M300**, which was triggered by a long press on the standby symbol and displayed with a red button illumination, will disappear.

Unfortunately, we can no longer comply with the latest EU directives on power consumption in deep standby with the current hardware and are therefore forced to remove this deep standby mode.

Alternatively, the **STUDIOMASTER** can be completely disconnected from the power supply using the mains switch.



Update messages on the front panel can be acknowledged again with the OK button. A restart is then triggered and the update is active.

Of course, we have also taken these changes into account in the operating instructions. You can find the latest version on our homepage and on the support page.

- **V400 AirPlay1**


The multiuser update 0.6.0 also fixes the intermittent AirPlay1 audio interruptions on the V400 multiuser server.

At this point, we would also like to draw your attention once again to our information sheet on AirPlay and the Multiuser system. The document, which can be [downloaded here](#), shows the difference between the two AirPlay versions and contains good practical tips.

- **Other changes and improvements**

In addition to the changes mentioned above, version 0.6.0 includes many other adjustments and bug fixes in the areas of alarm clock, KNX service, playback, search function and much more...

As usual, you can find an overview of the changes in the changelog, [here as a download](#), on our support page and of course in the multiuser app in the page list under Revox Info.



REVOX
Studio Sound Quality

Revox (Schweiz) AG
Eichwatt 5
CH 8105 Regensdorf

Revox Deutschland GmbH
Am Krebsgraben 15
D 78048 VS-Villingen

Revox Handels GmbH
Josef-Pirchl-Str. 38
AT 6370 Kitzbühel

[Recommend newsletter](#) | [Unsubscribe](#) | [Imprint](#)